


Platen shaft mod- instructions

Polish flow mod- To be tried after repeated polish priming has not worked. This is a quick and easy fix that , if it works, will last until it needs a service (years potentially)



Remove platen by lifting it straight up and out

Explanation- This area can get worn and by adding a layer of tape it can help move the polish pump

Task - Use household cellotape and wrap it around this area- ***only wrap around two times.***

Place back in the machine and prime in reverse for two minutes, leave 20 mins,
Prime forward for two minutes every 15 minutes until the polish flows.